

MARION COUNTY SURVEYOR'S OFFICE



SECTION CORNER RECORD

DEBRA S. JENKINS
MARION COUNTY SURVEYOR

SEC. 1 TWN. 15_N RNG. 4_E

BRYAN F. CATLIN, PLS
TECHNICAL SUPERVISOR

Date:10-13-09
Party Chief: Wilcoxen
Crew: Finney
Type of Marker: Harrison
Method of Establishment: County: 9-16-1998
IN S.P.C. E Zone, NAD 83
Name: 15040104
N: 502 734.733 4(m)
E: 67 564.515 1(m)



Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 30" beech bearing N 62 E 8 links and a 5" beech bearing S 73 W 19 links (Marion County Atlas p. 10). A survey by Hasbrook on 3/25/1850 indicates a rock set with the following witness: 10" elm bearing N 60.75 W 49 links. Corner is 30.70 chains (2026.20') S of the NW corner and 40.96 chains (2703.36') N of the S corner of 1-15-4 (Warren Legal Book p. 17). An undated survey by Fatout reports this corner 30.76 chains (2030.16') S of the NW corner of 1-15-4 (Warren legal Book p. 42). A Coyner survey at an unknown date in 1800's called rock set previously and being 2659.4' N of SW corner which results in a discrepancy of 43.96' with Hasbrook survey of 1850 (Warren Legal Book p. 64). In 5/1941 Indiana Project No:246(11) plans Sheet 5 a property corner is reported at STA 14+88, 7.5' right of survey line, and the NW corner of 1-15-4 is at STA 35+18.8, a stationing difference of 2030.8'. This distance compares favorably with Fatout survey distance of 2030.16. Corner referenced by Woerner on 6/18/48 and called a brass pin. Corner referenced by Monroe on 7/12/51 and called a brass plug. Surveys by Bloemker, Schneider, Weihe and Gary Piers from 1954-1993 make reference to this corner through deed calls. Corner was excavated by Wilcoxen on 7/30/95 and a brass plug was recovered 7.5' east of centerline. Distance from this plug and the plug at 10th& Shadeland verified stationing and distances to edges of pavement from 1948 support this to be West corner of 1-15-4. Corner excavated by Wilcoxen on 9/16/1998 and brass plug found 4" down. A 3.5" by 3.5" post was found 20" down under the brass plug. A # 205 cast iron Harrison Monument was set in position. 7/09/2003 Wilcoxen retied. 10/13/09 Wilcoxen retied.

REF.	DISTANCE	DESCRIPTION
1.	108.83'	NW corner of brick Jiffy Lube
2.	27.86'	Cut 'x' SW bolt of light pole base
3.	112.80'	SW corner of brick Jiffy Lube
4.	26.90'	SW corner of metal light control box
5.	106.45'	Cut 'x' N end of concrete headwall
6.	98.79'	Cut 'x' NE bolt of light pole base